



Starlight Instruments, LLC

2380 E. Cardinal Drive, Columbia City, Indiana 46725 USA

t: 260.244.0020 f.260.244.3077

e: sales@starlightinstruments.com

web: starlightinstruments.com

Focuser Boss II Firmware update instructions

- 1. goto file on the commander screen... hub must be turned on**
- 2. goto "upgrade firmware"**
- 3. goto "auto download", left click**
- 4. when auto download, is complete left click "upload now"**
- 5. "bootloader" box will appear left click ok**
- 6. Turn the power to the hub off and back on, this will allow the upload to Start.**

Uncompromising Quality and Craftsmanship for the Discriminating Amateur Astronomer

StarlightInstruments.com